

Oil Field Environmental Incident Summary

Incident: 20140915100827 **Date/Time of Notice:** 09/15/2014 10:08
Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION
Well Name: HALL #5-11H
Field Name: SPOTTED HORN **Well File #:** 20981
Date Incident: 9/14/2014 **Time Incident:** 11:16 **Facility ID Number:**
County: MCKENZIE **Twp:** 150 **Rng:** 94 **Sec:** 5 **Qtr:**
Location Description:

Submitted By: David Van der Vieren **Received By:**
Contact Person: Josh Ruffo
US BANK TOWER
950 17TH ST STE 2200
DENVER, CO 80202

General Land Use: Other - Described Above **Affected Medium:** Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine

Other	30	Barrels	30	Barrels	30	barrels
-------	----	---------	----	---------	----	---------

Description of Other Released Contaminant:

Produced Water

Inspected: **Written Report Received:** 7/27/2016 **Clean Up Concluded:** 9/29/2014

Risk Evaluation:

Run off risk was mitigated by building a temporary dyke.

Areal Extent:

Potential Environmental Impacts:

No long term impacts seen at this time.

Action Taken or Planned:

After third party trucking company spilled, a vac truck was called to site to recover liquids. Any waste will be disposed of at an approved disposal facility.

Wastes Disposal Location:

Agencies Involved: MHA,BIA,BLM

Updates

Date: 9/15/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.